

GOVERNMENT OF THE PEOPLE'S REPUBLIC OF BANGLADESH

MERCANTILE MARINE OFFICE

CHATTOGRAM

XXX ALL SHIPS VIA CHATTOGRAM RADIO.

NOTICE TO MARINERS NO 06 OF 2021

1. Bangladesh Navy have requested for Notice to Mariners is hereby promulgated in the **attached sheet's** (03 pages) co-ordinates:
2. B-1, B-3, B-4, B-5 and B-6 buoys of zulfiquar channel are placed in the same location with similar characteristics as shown in the aforementioned charts.
3. All Ships and Crafts are requested to incorporate necessary corrections on charts and navigate accordingly.

Authority:-

BNHOC Notice No. 08/2021)
New Mooring, Chattogram.

Not to be transmitted:-

To be broadcasted twice daily on 19TH and 20TH MARCH, 2021.



(Capt. Md. Giashuddin Ahmed)
Principal Officer
Mercantile Marine Office
Chattogram.
Phones: 724140, 721902

Distributed as in page.....2

DISTRIBUTION:

1. The Secretary, Ministry of Shipping, Dhaka.
2. The Director General, Dep't. of Shipping, BIWTA Bhaban, 141-143 Motijheel C/A, Dhaka-1000.
3. The Director of Naval Operation, Naval Headquarter, Banani, Dhaka.
4. The Director of Hydrographic, Naval H/Q, Operation Branch, Hydrographic Directorate, Banani, Dhaka.
5. The Commander Chittagong Naval Area, New Mooring, Chattogram.
6. The Commander Khulna, Naval Area, Khulna.
7. The Commodore Commanding BN Flotilla, New Mooring, Chattogram.
8. The Commodore, Naval Aviation, New mooring, Chattogram.
9. The Commodore, Swords Command, Board Bazar, Dangarchar, Patiya, Chattogram.
10. The Commanding Officer, BN Hydrographic & Ocean graphic Centre, New Mooring, Chattogram -4218.
11. The Bangladesh Coast Guard, Fisheries Academy Complex, Fish Harbour, Chattogram.
12. The Deputy Commissioner, Court Building, Chattogram.
13. The Commissioner of Customs, Custom House, Chattogram
14. The Chairman, Chittagong Port Authority, Chattogram
15. The Chairman, Mongla Port Authority, Mongla, Bagerhat.
16. The Station Master, Radio Sagargiri, Sitakundu, Chattogram.
17. The Deputy Conservator, Chittagong Port Authority, Chattogram.
18. The Regional Director, Bangladesh Betar, Chattogram -With request to broadcast the message both in English and Bengali.
19. The Controller, News Section, Bangladesh Betar, Chattogram.
20. The Engineer & Ship Surveyor, Mercantile Marine Office, Khalishpur, Khulna.
21. The Shipping Master, Govt. Shipping Office, CGO Building-1, Agrabad, Chattogram.
22. The Chairman, Civil Aviation Authority of Bangladesh, Kurmitola, Dhaka.
23. The Commandant, Artillery Centre & School, Halishahar, Chattogram.
24. The Airport Manager, Patenga, Chattogram.
25. M/S. Bangladesh Shipping Corporation, BSC Bhaban, Saltgola Road, Chattogram.
26. The BFDC, Fish Harbour, Chattogram.
27. The BIWTC, Sadarghat, Chattogram.
28. The BIWTA, Terminal Bhaban, Feringhee Bazar, Chattogram.
29. The President, Bangladesh Ocean going Ship Owners Association, House#11/B, (5th Floor), Road#30, Gulshan-1, Dhaka.
30. The Bangladesh Shipping Agents Association, Chamber House, Agrabad, Chattogram.
31. The Coastal Ship Owner Association of Bangladesh, Flat No. D-5, Silver Rain Tower, 48, Bijoy Nagar, Dhaka-1000.
32. The Bangladesh Oil Tanker Owners Association, Happy Rahman Plaza (4th Floor), 25-27 Kazi Nazrul Islam Avenue, Banglamotor, Dhaka-1000.
33. The Bangladesh Marine Fisheries Association, Madrasa Market, 4th Floor, 212/3 Kazi Nazrul Islam Road, Sadarghat, Chattogram
34. The Executive Director, Water Transport Co-ordination Cell, Kaderi Chamber (4th Floor), 37, Agrabad,, C/A, Ctg.
35. Bangladesh Marine Fisheries Boat Owners Association, Iqbal Road, Paterghata, Chattogram.
36. The Deep sea Boat Owners Samity, Fisherighat, Chattogram
37. The President, Cox's bazar District Fishing Boats Owners Association, Airport Road, Cox's Bazar.
38. Bangladesh Jatiya Matshajibi Samabaya Samity Ltd, Iqbal Road, Patherghata, Ctg.
39. The Hydrographic office, Admiralty way, Taunton, Somerset, London, TAI 2DN, U.K.
40. The Owners of all Fishing Trawlers.
41. M/S. -----



Principal Officer
Mercantile Marine Office, Chattogram.

: Attachment - 1 :

Insert


 <i>Fl.R.6s</i> B-20	21° 46'.15N, 89° 28'.27E
 <i>Fl(2)R.10s</i> B-22	21° 47'.38N, 89° 28'.63E
 <i>Fl(3)R.15s</i> B-24	21° 48'.32N, 89° 29'.81E
 <i>Fl(4)R.20s</i> B-26	21° 49'.24N, 89° 30'.65E
 <i>Fl(2)G.12s</i> BB-1	21° 38'.06N, 89° 30'.20E
 <i>Fl.G.8s</i> BB-3	21° 39'.64N, 89° 31'.05E
 <i>Fl.R.8s</i> BB-4	21° 39'.23N, 89° 29'.94E
 <i>Fl.10s</i> NK Buoy	21° 49'.03N, 89° 28'.75E

Delete

 <i>Fl(2)R.12s</i> B-8	21° 34'.38N, 89° 27'.17E
 <i>Fl(3)G.20s</i> B-9	21° 35'.87N, 89° 29'.12E
 <i>Fl.R.8s</i> B-10	21° 36'.34N, 89° 27'.90E
 <i>Fl(2)G.10s</i> B-11	21° 38'.01N, 89° 30'.31E
 <i>Fl(2)R.10s</i> B-12	21° 38'.00N, 89° 28'.96E
 <i>Fl.G.6s</i> B-13	21° 40'.04N, 89° 31'.15E
 <i>Fl.R.6s</i> B-14	21° 40'.04N, 89° 30'.25E
 <i>Fl(3)G.20s</i> B-19	21° 46'.52N, 89° 31'.38E
 <i>Fl.10s</i> Nil Kamal	21° 48'.82N, 89° 28'.78E















Amend


light- buoy to, <i>LFl.10s</i>	21° 26'.86N, 89° 33'.97E
light to, <i>FL(2).10s36m20M</i>	21° 47'.83N, 89° 28'.37E
light to, <i>FL(2).10s40m20M</i>	21° 45'.40N, 89° 32'.80E


 Principal Officer
 Mercantile Marine Office
 Govt. of Bangladesh
 Chattogram

: Attachment - 2 :

Insert

 FI(3)R.12s B-2	21° 27'.92N, 89° 30'.64E
 FI(2)G.12s B-7	21° 33'.88N, 89° 28'.70E
 FI(2)R.12s B-8	21° 33'.88N, 89° 27'.00E
 FI(3)G.15s B-9	21° 35'.98N, 89° 29'.53E
 FI(3)R.15s B-10	21° 35'.93N, 89° 26'.93E
 FI(2)G.12s B-11	21° 38'.42N, 89° 28'.31E
 FI(2)R.12s B-12	21° 38'.42N, 89° 26'.96E
 FI.G.8s B-13	21° 40'.05N, 89° 28'.63E
 FI.R.8s B-14	21° 40'.05N, 89° 27'.56E
 FI(4)G.15s B-15	21° 42'.09N, 89° 29'.08E
 FI(4)R.15s B-16	21° 42'.09N, 89° 28'.14E
 FI(2)G.10s B-17	21° 44'.12N, 89° 28'.94E
 FI(2)R.10s B-18	21° 44'.12N, 89° 28'.12E
 FI.G.6s B-19	21° 46'.15N, 89° 29'.14E


Principal Officer
Mercantile Marine Office
Govt. of Bangladesh
Chattogram

: Attachment - 3 :

Replace



FI(3)G.12s
B-15

with



FI(4)G.15s
BB-5

21° 41'.30N, 89° 31'.23E



FI(3)R.12s
B-16

with



FI(4)R.16s
BB-6

21° 41'.70N, 89° 29'.93E



FI.R.6s
B-20

with



FI.R.6s
BB-10

21° 46'.46N, 89° 29'.88E

Charts affected – BN 5001(INT 7426), BN 25001, BN 35001 (INT 7425) [WGS 84 DATUM]

Principal Officer
Mercantile Marine Office
Govt. of Bangladesh
Chattogram